# Work Order Bid (ID)

### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0099/1

Work Order Type: Weatherization Audit Name: 17017UC-0099

**CLIENT INFORMATION** 

Client ID: 17017UC-0099

#### **AGENCY INFORMATION**

Agency: Upper Cumberland H R A **Agency Phone:** (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax: Cookeville, TN 38506 **Email Address:** 

Agency Contact: Simcox, Tommy Work Phone:

Cell Phone: (931) 510-4384

**Email Address:** 

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1983 HOME 1488 SQ. FT

## **Measures**

-	Measure 1 Infil	tration Redctn		(	Componen	ts		I	Inspected
C	WATER	LK-FLOOR IN MASTER I R LINES IN BATH, BUILI EEDS WEATHERSTRIP	D 1 ATTIC	HATC			<b>o</b>		
Estimated Actual									
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Unit Cost	Total		
10	Miscellaneous Supplies	Infiltration Reduction	Each	1					
C	Other Detail								
				Measure	Sub Total:			Sub Total:	
	Field Notes:								
		dow Replacement	)		Componen	<i>t</i> s D10,C	7,D8	,	Inspected
		•	)		Componen Estimated	•	7,D8	Actual	Inspected
C		•	) Units	Qty	•	•	7,D8		Inspected
<i>C</i>	omment 4 WIND	OOWS NEED REPLACED			Estimated			Actual	
<b>C</b> #	omment 4 WIND	OOWS NEED REPLACED  Description / Comment	Units	Qty	Estimated			Actual	
<b>c</b> # 1	omment 4 WIND  Material / Labor  Windows	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36	Estimated			Actual	
<b>c</b> # 1	omment 4 WIND  Material / Labor  Windows  Labor	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36	Estimated			Actual	
<b>c</b> # 1	omment 4 WIND  Material / Labor  Windows  Labor	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36	Estimated			Actual	
<b>c</b> # 1	omment 4 WIND  Material / Labor  Windows  Labor	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36 41.36	Estimated		Qty	Actual	
# 1 2 C	omment 4 WIND  Material / Labor  Windows  Labor	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36 41.36	Estimated Unit Cost		Qty	Actual Unit Cost	
# 1 2 C	omment 4 WIND  Material / Labor  Windows  Labor  Other Detail	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36 41.36	Estimated Unit Cost		Qty	Actual Unit Cost	
# 1 2 C	omment 4 WIND  Material / Labor  Windows  Labor  Other Detail	DOWS NEED REPLACED  Description / Comment  Window Replacement	<i>Units</i> SqFt	<b>Qty</b> 41.36 41.36	Estimated Unit Cost		Qty	Actual Unit Cost	

1 Hot Water DF Equipment	escription / Comment			•	its		Inspected		
1 Hot Water Dh Equipment	escription / Comment								
1 Hot Water Dh Equipment	escription / Comment		Estimated			Actual			
Equipment		Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total	
R-	HW Tank Insulation	Each	1						
bu	-10 minimum-use ubble wrap								
2 Labor Dh	HW Tank Insulation	Each	1						
Other Detail						1			
			Measur	e Sub Total:		]	Sub Total:		
Measure 4 Attic Ins	s. R-38			Componer	nts AT1		,	Inspected	
	s. R-38			Componer Estimated			Actual	Inspected	
Comment	s. R-38 escription / Comment	Units	Qty	-		Qty		Inspected Total	
Comment  # Material / Labor De  Insulation At		<i>Units</i> SqFt		Estimated	1	Qty	Actual		
Comment  # Material / Labor De  Insulation At	escription / Comment ttic Insulation - Blown		Qty	Estimated	1	Qty	Actual		
Comment  # Material / Labor De  Insulation At	escription / Comment ttic Insulation - Blown		Qty	Estimated	1	Qty	Actual		
Comment  # Material / Labor De  Insulation At	escription / Comment ttic Insulation - Blown		Qty	Estimated	1	Qty	Actual		
Comment  # Material / Labor De  Insulation At	escription / Comment ttic Insulation - Blown	SqFt	<b>Qty</b> 1488	Estimated	1		Actual		

	Moisture Problems sement/Crawlspace)		Components			Inspected			
<b>Comment</b> HOUSI	E HAS LOTS OF MOISTUI	RE PROE	BLEMS						
				Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total	
10 Unspecified	Moisture Barrier Needed (+)	Each	1						
Other Detail									
			Measur	e Sub Total:		] ;	Sub Total:		
Field Notes:									
	Γ								
		Work Or	der Gra	nd Total:		Gran	d Total:		